

Receiver Connection Warning

UNDER NO CIRCUMSTANCES INSTALL ANY OF THE POWEREXPANDER RECEIVER CONNECTIONS INTO ANY BATTERY PORT ON THE RECEIVER.

Installing any of the receiver connections from the PowerExpander into any receiver battery port may cause the receiver to malfunction. On a PCM receiver it will most likely put the receiver into Direct Servo Control (DSC) mode where it will stop listening to the transmitter. Putting a receiver connector into a BAT/BIND port on a 2.4GHz receiver may cause the receiver to unbind at some unpredictable time. Receiver connections from the PowerExpander to the receiver should **ONLY** go into servo output ports. If you have any questions about this warning please call us at (480) 460-2652. Thank you.

—

Receiver Connection Warning

UNDER NO CIRCUMSTANCES INSTALL ANY OF THE POWEREXPANDER RECEIVER CONNECTIONS INTO ANY BATTERY PORT ON THE RECEIVER.

Installing any of the receiver connections from the PowerExpander into any receiver battery port may cause the receiver to malfunction. On a PCM receiver it will most likely put the receiver into Direct Servo Control (DSC) mode where it will stop listening to the transmitter. Putting a receiver connector into a BAT/BIND port on a 2.4GHz receiver may cause the receiver to unbind at some unpredictable time. Receiver connections from the PowerExpander to the receiver should **ONLY** go into servo output ports. If you have any questions about this warning please call us at (480) 460-2652. Thank you.

—

Receiver Connection Warning

UNDER NO CIRCUMSTANCES INSTALL ANY OF THE POWEREXPANDER RECEIVER CONNECTIONS INTO ANY BATTERY PORT ON THE RECEIVER.

Installing any of the receiver connections from the PowerExpander into any receiver battery port may cause the receiver to malfunction. On a PCM receiver it will most likely put the receiver into Direct Servo Control (DSC) mode where it will stop listening to the transmitter. Putting a receiver connector into a BAT/BIND port on a 2.4GHz receiver may cause the receiver to unbind at some unpredictable time. Receiver connections from the PowerExpander to the receiver should **ONLY** go into servo output ports. If you have any questions about this warning please call us at (480) 460-2652. Thank you.